SEU

WORKORDER

WORK ORDER #: 6115599

PARENT WO #:

DESCRIPTION: VALVE TESTING SS-10 (SEE COMMENTS BELOW)

037-00040

TARGET START DATE:

TARGET COMP DATE: 5/5/2016

SCHEDULE START:

SCHEDULE FINISH:

ROUTE NUMBER:

PMNUM:

STATUS: COMP

REQUESTED BY: DMAINE REPORT DATE: 4/11/2016

PM ACTIVITY CLASS:

ASSET #: 24849

ASSET DESCRIPTION: GROUP 5 WELLS

LOCATION ID: AC-GROUP 5 WELLS

LOC. DESCRIPTION: PORTER 25R, 38, 39, 40, 47, PS-42, SS-2, 3, 5, 6,

SS-7, 8, 9, 10, 11, 17, 24, 31

PHYSICAL LOCATION:

RESPONSIBLE SUPERVISOR / OWNER

WORK TYPE CM

PRIORITY 2

ACCOUNT_INFO

26357.003

FIELD MAINT / REMARKS: PERFORMED FUNCTION

TEST UN 4-21-16

ALL VALUES LISTED BELOW Date Completed

MACK OCHOA Completed By

SAFETY CHECKLIST COMPLETED?

Estimated Labor Hours

Labor Code/Craft

Quantity

Planned Hours

0

JTMACK

COMMENTS:

JOCHOA!

,25

PERFORM FUNCTION TEST ON THE MASTER VALVE, TUBING PRODUCTION WING VALVE, CASING PRODUCTION WING VALVE, TUBING KILL WING VALVE & CASING KILL WING VALVE.

LOCATION METERS:

LOG:

CLIENTNOTE

BY: DMAINE

CREATED: Apr 20, 2016, 10:57 AM

Description:

UNABLE TO FUNCTION THE CASING PRODUCTION WING VALVE. " DO NOT OPERATE": ALL OTHER VALVES COMPLETED <! -- RICH TEXT -->